TxMAS Contract No. TXMAS-8-56010 Effective: May 15, 2006 - May 14, 2011



Phone: (480) 768-1618 Facsimile: (480) 768-1514

2 x 4 Buildings - 4' On-Center

			SIN 361-10A			
				Truss		
Width	Length	Eave Height	Peak Height	Clearance	GSA West	GSA East
Prices includ	e shipping to the	nearest freight	terminal for the	frame & the \$75.	00 del fee from F	abral you will
	need to add \$10	0 if they require	a Boom Truck D		able in their area	
14	24	13.5	15 3/4	13' 4"	\$7,984.18	\$8,782.60
14	28	13.5	15 3/4	13' 4"	\$8,936.51	\$9,830.16
14	32	13.5	15 3/4	13' 4"	\$9,888.83	\$10,877.71
14	36	13.5	15 3/4	13' 4"	\$10,841.15	\$11,925.26
14	40	13.5	15 3/4	13' 4"	\$11,793.47	\$12,972.82
14	44	13.5	15 3/4	13' 4"	\$12,705.33	\$13,975.86
14	48	13.5	15 3/4	13' 4"	\$13,859.97	\$15,245.96
14	52	13.5	15 3/4	13' 4"	\$15,014.60	\$16,516.06
14	56	13.5	15 3/4	13' 4"	\$16,170.68	\$17,787.75
14	60	13.5	15 3/4	13' 4"	\$17,325.32	\$19,057.85
14	64	13.5	15 3/4	13' 4"	\$17,742.95	\$19,517.25
14	68	13.5	15 3/4	13' 4"	\$19,634.59	\$21,598.05
14	72	13.5	15 3/4	13' 4"	\$20,790.67	\$22,869.74
14	76	13.5	15 3/4	13' 4"	\$21,945.31	\$24,139.84
14	80	13.5	15 3/4	13' 4"	\$23,099.94	\$25,409.94
14	84	13.5	15 3/4	13' 4"	\$24,256.02	\$26,681.63
14	88	13.5	15 3/4	13' 4"	\$25,410.66	\$27,951.73
14	92	13.5	15 3/4	13' 4"	\$26,565.30	\$29,221.83
14	96	13.5	15 3/4	13' 4"	\$27,721.38	\$30,493.52
14	100	13.5	15 3/4	13' 4"	\$28,876.01	\$31,763.61
14	24	14.5	16 3/4	14' 4"	\$8,575.61	\$9,433.17
14	28	14.5	16 3/4	14' 4"	\$9,598.47	\$10,558.32
14	32	14.5	16 3/4	14' 4"	\$10,621.33	\$11,683.47
14	36	14.5	16 3/4	14' 4"	\$11,644.20	\$12,808.62
14	40	14.5	16 3/4	14' 4"	\$12,667.06	\$13,933.77
14	44	14.5	16 3/4	14' 4"	\$13,646.47	\$15,011.11
14	48	14.5	16 3/4	14' 4"	\$14,886.63	\$16,375.29
14	52	14.5	16 3/4	14' 4"	\$16,126.79	\$17,739.47
14	56	14.5	16 3/4	14' 4"	\$17,368.51	\$19,105.36
14	60	14.5	16 3/4	14' 4"	\$18,608.68	\$20,469.54
14	64	14.5	16 3/4	14' 4"	\$19,057.25	\$20,962.97
14	68	14.5	16 3/4	14' 4"	\$21,089.00	\$23,197.91
14	72	14.5	16 3/4	14' 4"	\$22,330.72	\$24,563.79
14	76	14.5	16 3/4	14' 4"	\$23,570.89	\$25,927.97
14	80	14.5	16 3/4	14' 4"	\$24,811.05	\$27,292.16
14	84	14.5	16 3/4	14' 4"	\$26,052.77	\$28,658.04
14	88	14.5	16 3/4	14' 4"	\$27,292.93	\$30,022.22
14	92	14.5	16 3/4	14' 4"	\$28,533.10	\$31,386.41
14	96	14.5	16 3/4	14' 4"	\$29,774.81	\$32,752.29
14	100	14.5	16 3/4	14' 4"	\$31,014.98	\$34,116.48
14	24	15.5	17 3/4	15' 4"	\$9,167.03	\$10,083.73
14	28	15.5	17 3/4	15' 4"	\$10,260.43	\$11,286.48
14	32	15.5	17 3/4	15' 4"	\$11,353.84	\$12,489.22

Width	Length	Eave Height	Peak Height	Truss Clearance	GSA West	GSA East
14	36	15.5	17 3/4	15' 4"	\$12,447.25	\$13,691.97
14	40	15.5	17 3/4	15' 4"	\$13,540.65	\$14,894.72
14	44	15.5	17 3/4	15' 4"	\$14,587.60	\$16,046.36
14	48	15.5	17 3/4	15' 4"	\$15,913.29	\$17,504.62
14	52	15.5	17 3/4	15' 4"	\$17,238.99	\$18,962.89
14	56	15.5	17 3/4	15' 4"	\$18,566.34	\$20,422.97
14	60	15.5	17 3/4	15' 4"	\$19,892.03	\$21,881.24
14	64	15.5	17 3/4	15' 4"	\$20,371.54	\$22,408.69
14	68	15.5	17 3/4	15' 4"	\$22,543.42	\$24,797.76
14	72	15.5	17 3/4	15' 4"	\$23,870.77	\$26,257.85
14	76	15.5	17 3/4	15' 4"	\$25,196.46	\$27,716.11
14	80	15.5	17 3/4	15' 4"	\$26,522.16	\$29,174.37
14	84	15.5	17 3/4	15' 4"	\$27,849.51	\$30,634.46
14	88	15.5	17 3/4	15' 4"	\$29,175.20	\$32,092.72
14	92	15.5	17 3/4	15' 4"	\$30,500.90	\$33,550.99
14	96	15.5	17 3/4	15' 4"	\$31,828.25	\$35,011.07
14	100	15.5	17 3/4	15' 4"	\$33,153.94	\$36,469.34
20	24	13.5	16 3/4	13' 4"	\$10,761.67	\$11,837.84
20	28	13.5	16 3/4	13' 4"	\$12,173.53	\$13,390.89
20	32	13.5	16 3/4	13' 4"	\$13,568.06	\$14,924.86
20	36	13.5	16 3/4	13' 4"	\$14,964.02	\$16,460.43
20	40	13.5	16 3/4	13' 4"	\$16,358.55	\$17,994.40
20	44	13.5	16 3/4	13' 4"	\$17,728.50	\$19,501.35
20	48	13.5	16 3/4	13' 4"	\$19,341.24	\$21,275.36
20	52	13.5	16 3/4	13' 4"	\$20,952.52	\$23,047.78
20	56	13.5	16 3/4	13' 4"	\$22,565.26	\$24,821.78
20	60	13.5	16 3/4	13' 4"	\$24,176.54	\$26,594.20
20	64	13.5	16 3/4	13' 4"	\$25,787.83	\$28,366.62
20	68	13.5	16 3/4	13' 4"	\$27,400.56	\$30,140.62
20	72	13.5	16 3/4	13' 4"	\$29,011.85	\$31,913.04
20	76	13.5	16 3/4	13' 4"	\$30,623.14	\$33,685.45
20	80	13.5	16 3/4	13' 4"	\$32,235.87	\$35,459.46
20	84	13.5	16 3/4	13' 4"	\$33,847.16	\$37,231.88
20	88	13.5	16 3/4	13' 4"	\$35,458.45	\$39,004.29
20	92	13.5	16 3/4	13' 4"	\$37,071.18	\$40,778.30
20	96	13.5	16 3/4	13' 4"	\$38,682.47	\$42,550.72
20	100	13.5	16 3/4	13' 4"	\$40,293.76	\$44,323.13
20	24	14.5	17 3/4	14' 4"	\$11,558.83	\$12,714.71
20	28	14.5	17 3/4	14' 4"	\$13,075.28	\$14,382.80
20	32	14.5	17 3/4	14' 4"	\$14,573.10	\$16,030.41
20	36	14.5	17 3/4	14' 4"	\$16,072.47	\$17,679.72
20	40	14.5	17 3/4	14' 4"	\$17,570.29	\$19,327.32
20	44	14.5	17 3/4	14' 4"	\$19,041.72	\$20,945.90
20	48	14.5	17 3/4	14' 4"	\$20,773.92	\$22,851.31
20	52	14.5	17 3/4	<u> </u>	\$22,504.56	\$24,755.02 \$26,660,42
20 20	56 60	14.5 14.5	17 3/4 17 3/4	14' 4"	\$24,236.76 \$25,967,40	\$26,660.43 \$28,564,14
20	60 64	14.5	17 3/4	14 4	\$25,967.40 \$27,698.04	\$28,564.14 \$30,467.85
20	68	14.5	17 3/4	14 4	\$29,430.24	\$32,373.26
20	72	14.5	17 3/4	14 4	\$31,160.88	\$34,276.97
20	72	14.5	17 3/4	14 4	\$32,891.52	\$36,180.67
20	80	14.5	17 3/4	14 4	\$34,623.72	\$38,086.09
20	84	14.5	17 3/4	14 4	\$36,354.36	\$39,989.79
20	04	14.5	17 3/4	14 4		φ39,909.79 uthorized Price I

Width	Length	Eave Height	Peak Height	Truss Clearance	GSA West	GSA East
20	88	14.5	17 3/4	14' 4"	\$38,085.00	\$41,893.50
20	92	14.5	17 3/4	14' 4"	\$39,817.20	\$43,798.92
20	96	14.5	17 3/4	14' 4"	\$41,547.84	\$45,702.62
20	100	14.5	17 3/4	14' 4"	\$43,278.48	\$47,606.33
20	24	15.5	18 3/4	15' 4"	\$12,355.99	\$13,591.59
20	28	15.5	18 3/4	15' 4"	\$13,977.02	\$15,374.72
20	32	15.5	18 3/4	15' 4"	\$15,578.14	\$17,135.95
20	36	15.5	18 3/4	15' 4"	\$17,180.92	\$18,899.01
20	40	15.5	18 3/4	15' 4"	\$18,782.03	\$20,660.24
20	44	15.5	18 3/4	15' 4"	\$20,354.95	\$22,390.44
20	48	15.5	18 3/4	15' 4"	\$22,206.60	\$24,427.26
20	52	15.5	18 3/4	15' 4"	\$24,056.60	\$26,462.26
20	56	15.5	18 3/4	15' 4"	\$25,908.26	\$28,499.08
20	60	15.5	18 3/4	15' 4"	\$27,758.25	\$30,534.08
20	64	15.5	18 3/4	15' 4"	\$29,608.25	\$32,569.08
20	68	15.5	18 3/4	15' 4"	\$31,459.91	\$34,605.90
20	72	15.5	18 3/4	15' 4"	\$33,309.91	\$36,640.90
20	76	15.5	18 3/4	15' 4"	\$35,159.90	\$38,675.89
20	80	15.5	18 3/4	15' 4"	\$37,011.56	\$40,712.71
20	84	15.5	18 3/4	15' 4"	\$38,861.56	\$42,747.71
20	88	15.5	18 3/4	15' 4"	\$40,711.55	\$44,782.71
20	92	15.5	18 3/4	15' 4"	\$42,563.21	\$46,819.53
20	96	15.5	18 3/4	15' 4"	\$44,413.21	\$48,854.53
20	100	15.5	18 3/4	15' 4"	\$46,263.20	\$50,889.52
24	24	13.5	17 2/4	13' 4"	\$11,530.46	\$12,683.51
24	28	13.5	17 2/4	13' 4"	\$13,037.70	\$14,341.47
24	32	13.5	17 2/4	13' 4"	\$14,527.60	\$15,980.36
24	36	13.5	17 2/4	13' 4"	\$16,017.50	\$17,619.25
24	40	13.5	17 2/4	13' 4"	\$17,505.96	\$19,256.55
24	44	13.5	17 2/4	13' 4"	\$18,971.29	\$20,868.42
24	48	13.5	17 2/4	13' 4"	\$20,696.74	\$22,766.41
24	52	13.5	17 2/4	13' 4"	\$22,420.75	\$24,662.82
24	56	13.5	17 2/4	13' 4"	\$24,146.20	\$26,560.82
24	60	13.5	17 2/4	13' 4"	\$25,870.20	\$28,457.22
24	64	13.5	17 2/4	13' 4"	\$27,595.65	\$30,355.22
24	68	13.5	17 2/4	13' 4"	\$29,319.66	\$32,251.63
24	72	13.5	17 2/4	13' 4"	\$31,045.11	\$34,149.62
24	76	13.5	17 2/4	13' 4"	\$32,770.56	\$36,047.62
24	80	13.5	17 2/4	13' 4"	\$34,494.57	\$37,944.02
24	84	13.5	17 2/4	13' 4"	\$36,220.02	\$39,842.02
24	88	13.5	17 2/4	13' 4"	\$37,944.02	\$41,738.43
24	92	13.5	17 2/4	13' 4"	\$39,669.47	\$43,636.42
24	96	13.5	17 2/4	13' 4"	\$41,393.48	\$45,532.83
24	100	13.5	17 2/4	13' 4"	\$43,118.93	\$47,430.82
24	24	14.5	18 2/4	14' 4"	\$12,384.57	\$13,623.03
24	28	14.5	18 2/4	14' 4"	\$14,003.46	\$15,403.81
24	32	14.5	18 2/4	14' 4"	\$15,603.72	\$17,164.09
24	36	14.5	18 2/4	14' 4"	\$17,203.98	\$18,924.38
24	40	14.5	18 2/4	14' 4"	\$18,802.69	\$20,682.96
24	44	14.5	18 2/4	14' 4"	\$20,376.57	\$22,414.23
24	48	14.5	18 2/4	14' 4"	\$22,229.83	\$24,452.82
24	52	14.5	18 2/4	14' 4"	\$24,081.54	\$26,489.70
24	56	14.5	18 2/4	14' 4"	\$25,934.80	\$28,528.28

				Truss		
Width	Length	Eave Height	Peak Height	Clearance	GSA West	GSA East
24	60	14.5	18 2/4	14' 4"	\$27,786.51	\$30,565.17
24	64	14.5	18 2/4	14' 4"	\$29,639.78	\$32,603.75
24	68	14.5	18 2/4	14' 4"	\$31,491.49	\$34,640.63
24	72	14.5	18 2/4	14' 4"	\$33,344.75	\$36,679.22
24	76	14.5	18 2/4	14' 4"	\$35,198.01	\$38,717.81
24	80	14.5	18 2/4	14' 4"	\$37,049.72	\$40,754.69
24	84	14.5	18 2/4	14' 4"	\$38,902.98	\$42,793.28
24	88	14.5	18 2/4	14' 4"	\$40,754.69	\$44,830.16
24	92	14.5	18 2/4	14' 4"	\$42,607.95	\$46,868.75
24	96	14.5	18 2/4	14' 4"	\$44,459.66	\$48,905.63
24	100	14.5	18 2/4	14' 4"	\$46,312.93	\$50,944.22
24	24	15.5	19 2/4	15' 4"	\$13,238.68	\$14,562.55
24	28	15.5	19 2/4	15' 4"	\$14,969.22	\$16,466.14
24	32	15.5	19 2/4	15' 4"	\$16,679.84	\$18,347.82
24	36	15.5	19 2/4	15' 4"	\$18,390.47	\$20,229.51
24	40	15.5	19 2/4	15' 4"	\$20,099.43	\$22,109.37
24	44	15.5	19 2/4	15' 4"	\$21,781.85	\$23,960.04
24	48	15.5	19 2/4	15' 4"	\$23,762.92	\$26,139.22
24	52	15.5	19 2/4	15' 4"	\$25,742.34	\$28,316.57
24	56	15.5	19 2/4	15' 4"	\$27,723.41	\$30,495.75
24	60	15.5	19 2/4	15' 4"	\$29,702.83	\$32,673.11
24	64	15.5	19 2/4	15' 4"	\$31,683.90	\$34,852.29
24	68	15.5	19 2/4	15' 4"	\$33,663.31	\$37,029.64
24	72	15.5	19 2/4	15' 4"	\$35,644.39	\$39,208.82
24	76	15.5	19 2/4	15' 4"	\$37,625.46	\$41,388.01
24	80	15.5	19 2/4	15' 4"	\$39,604.87	\$43,565.36
24	84	15.5	19 2/4	15' 4"	\$41,585.95	\$45,744.54
24	88	15.5	19 2/4	15' 4"	\$43,565.36	\$47,921.90
24	92	15.5	19 2/4	15' 4"	\$45,546.43	\$50,101.08
24	96	15.5	19 2/4	15' 4"	\$47,525.85	\$52,278.43
24	100	15.5	19 2/4	15' 4"	\$49,506.92	\$54,457.61
30	24	13.5	18 2/4	13' 4"	\$12,763.13	\$14,039.45
30	28	13.5	18 2/4	13' 4"	\$14,381.65	\$15,819.81
30	32	13.5	18 2/4	13' 4"	\$16,017.50	\$17,619.25
30	36	13.5	18 2/4	13' 4"	\$17,653.36	\$19,418.69
30	40	13.5	18 2/4	13' 4"	\$19,270.43	\$21,197.47
30	44	13.5	18 2/4	13' 4"	\$20,864.37	\$22,950.81
30	48	13.5	18 2/4	13' 4"	\$22,761.79	\$25,037.97
30	52	13.5	18 2/4	13' 4"	\$24,659.21	\$27,125.13
30	56	13.5	18 2/4	13' 4"	\$26,555.18	\$29,210.70
30	60	13.5	18 2/4	13' 4"	\$28,452.60	\$31,297.86
30	64	13.5	18 2/4	13' 4"	\$30,350.02	\$33,385.02
30	68	13.5	18 2/4	13' 4"	\$32,245.99	\$35,385.02
30	72	13.5	18 2/4	13' 4"	\$34,143.41	\$37,557.75
30	72	13.5	18 2/4	13' 4"	\$36,039.38	\$39,643.32
30	80	13.5	18 2/4	13' 4"	\$37,936.80	\$41,730.48
30	84	13.5	18 2/4	13' 4"	\$39,834.22	\$43,817.64
30	88	13.5	18 2/4	13' 4"	\$41,730.19	\$45,903.21
30	92			13 4		
		13.5	18 2/4	13' 4"	\$43,627.61	\$47,990.37 \$50.077.52
30	96	13.5	18 2/4		\$45,525.02	\$50,077.53 \$52,162,10
30	100	13.5	18 2/4	13' 4"	\$47,421.00	\$52,163.10
30	24	14.5	19 2/4	14' 4"	\$13,708.55	\$15,079.41
30	28	14.5	19 2/4	14' 4"	\$15,446.95	\$16,991.65 wthorized Price

$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	Width	Length	Eave Height	Peak Height	Truss Clearance	GSA West	GSA East
$\begin{array}{c c c c c c c c c c c c c c c c c c c $				_			
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$							
304414.519 2/414'4"\$22,409.88\$24,65304814.519 2/414'4"\$24,447.85\$26,89305214.519 2/414'4"\$26,468.82\$22,913305614.519 2/414'4"\$26,522.23\$31,37306014.519 2/414'4"\$32,509.17\$33,661306414.519 2/414'4"\$32,509.17\$35,655306814.519 2/414'4"\$34,634.58\$38,099307214.519 2/414'4"\$36,672.55\$40,33307614.519 2/414'4"\$36,670.969\$42,57308014.519 2/414'4"\$44,781.90\$47,061308414.519 2/414'4"\$44,821.31\$49,30309214.519 2/414'4"\$44,821.31\$49,30309214.519 2/414'4"\$44,821.31\$49,30309614.519 2/414'4"\$48,897.28\$53,7830302415.520 2/415'4"\$16,51.26\$16,11302815.520 2/415'4"\$16,61.26\$18,16303215.520 2/415'4"\$22,21.25.39\$20,22303615.520 2/415'4"\$33,80.47\$20,22303615.520 2/415'4"\$34,86.33,97\$4							\$22,767.65
304814.5191914'4''\$24,447,85\$26,89305214.5191914'4''\$26,485,82\$29,13305614.5191914'4''\$32,681,7\$33,611306014.5192/414'4''\$34,634,58\$38,09306814.5192/414'4''\$34,635,88,07\$33,611306814.5192/414'4''\$34,635,88,09307214.5192/414'\$34,635,88,09\$42,577308014.5192/414'\$44,784,90\$47,06308414.5192/414'\$44,821,31\$49,30309214.5192/414'\$44,821,31\$49,30309614.5192/414'\$44,821,31\$49,30309614.5192/414'\$44,821,31\$49,30309614.5192/414'\$44,821,31\$43,30302415.5202/415'\$16,11302815.5202/415'\$20,224303615.5202/415'\$20,22430304015.5202/415'\$20,224,33304415.5202/415'\$22,283,55,393							\$24,650.87
305214.519 2/414' 4"\$26,485,82\$29,13305614.519 2/414' 4"\$30,560.20\$33,61306014.519 2/414' 4"\$30,560.20\$33,61306414.519 2/414' 4"\$34,634,58\$38,09306814.519 2/414' 4"\$34,634,58\$38,09307214.519 2/414' 4"\$34,634,58\$38,09307614.519 2/414' 4"\$34,634,58\$38,096308014.519 2/414' 4"\$40,746,39\$44,257308414.519 2/414' 4"\$44,689,28\$42,57308414.519 2/414' 4"\$44,689,28\$44,930309214.519 2/414' 4"\$44,689,28\$55,378309614.519 2/414' 4"\$46,859,28\$55,3783010014.519 2/414' 4"\$46,859,28\$55,378302415.520 2/415' 4"\$14,653,97\$16,111302815.520 2/415' 4"\$22,28,67\$22,29303615.520 2/415' 4"\$22,28,67\$22,2930304415.520 2/415' 4"\$22,125,30\$22,22303615.520 2/415' 4"\$32,667,80\$35,93304415.520 2/415' 4"\$32							\$26,892.63
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$							\$29,134.40
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$31,374.45
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$							\$33,616.22
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$35,857.98
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$38,098.04
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$40,339.80
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$42,579.86
308414.519 2/414' 4"\$42,784.90\$47,063308814.519 2/414' 4"\$44,821.31\$49,304309214.519 2/414' 4"\$46,859.28\$51,54309614.519 2/414' 4"\$48,897.25\$53,7843010014.519 2/414' 4"\$50,933.66\$56,022302415.520 2/415' 4"\$14,653.97\$16,113302815.520 2/415' 4"\$16,512.26\$18,166303215.520 2/415' 4"\$20,228.67\$22,293303615.520 2/415' 4"\$22,125.30\$24,333304015.520 2/415' 4"\$22,125.30\$24,333304415.520 2/415' 4"\$22,125.30\$24,333304815.520 2/415' 4"\$22,125.30\$24,333305215.520 2/415' 4"\$32,667.80\$33,533306015.520 2/415' 4"\$33,049.28\$33,533306415.520 2/415' 4"\$33,049.28\$33,533306815.520 2/415' 4"\$34,846.32\$38,333306815.520 2/415' 4"\$34,846.32\$38,333306815.520 2/415' 4"\$41,378.55\$45,51130307615.520 2/415' 4"							\$44,821.62
308814.519 2/414' 4"\$44,821.31\$49,30309214.519 2/414' 4"\$46,859.28\$51,54309614.519 2/414' 4"\$46,859.28\$53,783010014.519 2/414' 4"\$60,933.66\$56,02302415.520 2/415' 4"\$16,512.26\$18,16302815.520 2/415' 4"\$16,512.26\$18,16303215.520 2/415' 4"\$20,268.77\$22,29303615.520 2/415' 4"\$22,246.33304015.520 2/415' 4"\$22,24.33304015.520 2/415' 4"\$22,24.33304415.520 2/415' 4"\$22,125.30304815.520 2/415' 4"\$23,955.39305215.520 2/415' 4"\$28,312.42305215.520 2/415' 4"\$30,489.28306015.520 2/415' 4"\$30,489.28306415.520 2/415' 4"\$33,03.53306815.520 2/415' 4"\$34,846.32307615.520 2/415' 4"\$34,846.32307615.520 2/415' 4"\$44,355.706308015.520 2/415' 4"\$45,735.58308015.520 2/415' 4"							\$47,063.39
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$49,303.45
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$51,545.21
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$53,786.97
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$56,027.03
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$16,119.37
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$18,163.49
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$20,229.51
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$22,295.54
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$24,337.83
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$26,350.93
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$28,747.30
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$31,143.67
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$33,538.21
30 64 15.5 $20 2/4$ $15' 4"$ $$34,846.32$ $$38,330$ 30 68 15.5 $20 2/4$ $15' 4"$ $$37,023.17$ $$40,722$ 30 72 15.5 $20 2/4$ $15' 4"$ $$39,201.69$ $$43,12'$ 30 76 15.5 $20 2/4$ $15' 4"$ $$41,378.55$ $$45,516$ 30 80 15.5 $20 2/4$ $15' 4"$ $$43,557.06$ $$47,912$ 30 80 15.5 $20 2/4$ $15' 4"$ $$43,557.06$ $$47,912$ 30 84 15.5 $20 2/4$ $15' 4"$ $$45,735.58$ $$50,309$ 30 84 15.5 $20 2/4$ $15' 4"$ $$47,912.44$ $$52,700$ 30 92 15.5 $20 2/4$ $15' 4"$ $$50,090.96$ $$55,100$ 30 96 15.5 $20 2/4$ $15' 4"$ $$52,269.47$ $$57,496$ 30 100 15.5 $20 2/4$ $15' 4"$ $$54,446.33$ $$59,896$ 35 24 10.5 $16 1/4$ $10' 4"$ $$12,614.98$ $$13,876$ 35 32 10.5 $16 1/4$ $10' 4"$ $$13,823.24$ $$15,203$ 35 36 10.5 $16 1/4$ $10' 4"$ $$16,236.65$ $$17,866$ 35 40 10.5 $16 1/4$ $10' 4"$ $$16,236.65$ $$17,866$							\$35,934.58
306815.520 2/415' 4" $\$37,023.17$ $\$40,724$ 307215.520 2/415' 4" $\$39,201.69$ $\$43,12$ 307615.520 2/415' 4" $\$41,378.55$ $\$45,516$ 308015.520 2/415' 4" $\$43,557.06$ $\$47,912$ 308415.520 2/415' 4" $\$43,557.06$ $\$47,912$ 308415.520 2/415' 4" $\$45,735.58$ $\$50,309$ 308815.520 2/415' 4" $\$47,912.44$ $\$52,703$ 309215.520 2/415' 4" $\$50,090.96$ $\$55,100$ 309615.520 2/415' 4" $\$52,269.47$ $\$57,496$ 3010015.520 2/415' 4" $\$52,269.47$ $\$57,496$ 352410.516 1/410' 4" $\$13,823.24$ $\$13,876$ 353610.516 1/410' 4" $\$13,823.24$ $\$15,209$ 353610.516 1/410' 4" $\$16,236.65$ $\$17,866$ 354010.516 1/410' 4" $\$17,443.35$ $\$19,181$							\$38,330.95
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$40,725.49
$\begin{array}{c c c c c c c c c c c c c c c c c c c $							\$43,121.86
30 80 15.5 20 2/4 15' 4" \$43,557.06 \$47,912 30 84 15.5 20 2/4 15' 4" \$45,735.58 \$50,309 30 88 15.5 20 2/4 15' 4" \$47,912.44 \$52,703 30 92 15.5 20 2/4 15' 4" \$47,912.44 \$52,703 30 92 15.5 20 2/4 15' 4" \$50,090.96 \$55,100 30 96 15.5 20 2/4 15' 4" \$52,269.47 \$57,496 30 96 15.5 20 2/4 15' 4" \$54,446.33 \$59,890 35 24 10.5 16 1/4 10' 4" \$12,614.98 \$13,876 35 28 10.5 16 1/4 10' 4" \$13,823.24 \$15,209 35 32 10.5 16 1/4 10' 4" \$15,029.95 \$16,532 35 36 10.5 16 1/4 10' 4" \$16,236.65 \$17,860 35 4							\$45,516.40
30 84 15.5 20 2/4 15' 4" \$45,735.58 \$50,309 30 88 15.5 20 2/4 15' 4" \$47,912.44 \$52,703 30 92 15.5 20 2/4 15' 4" \$50,090.96 \$55,100 30 92 15.5 20 2/4 15' 4" \$52,269.47 \$57,496 30 96 15.5 20 2/4 15' 4" \$54,446.33 \$59,890 30 100 15.5 20 2/4 15' 4" \$54,446.33 \$59,890 35 24 10.5 16 1/4 10' 4" \$13,823.24 \$13,876 35 28 10.5 16 1/4 10' 4" \$13,823.24 \$15,209 35 32 10.5 16 1/4 10' 4" \$15,029.95 \$16,537 35 36 10.5 16 1/4 10' 4" \$16,236.65 \$17,860 35 40 10.5 16 1/4 10' 4" \$17,443.35 \$19,187							\$47,912.77
30 88 15.5 20 2/4 15' 4" \$47,912.44 \$52,703 30 92 15.5 20 2/4 15' 4" \$50,090.96 \$55,100 30 96 15.5 20 2/4 15' 4" \$52,269.47 \$57,496 30 100 15.5 20 2/4 15' 4" \$54,446.33 \$59,890 35 24 10.5 16 1/4 10' 4" \$12,614.98 \$13,876 35 28 10.5 16 1/4 10' 4" \$13,823.24 \$15,200 35 32 10.5 16 1/4 10' 4" \$15,029.95 \$16,532 35 36 10.5 16 1/4 10' 4" \$16,236.65 \$17,860 35 36 10.5 16 1/4 10' 4" \$16,236.65 \$17,860 35 40 10.5 16 1/4 10' 4" \$17,443.35 \$19,181						. ,	\$50,309.14
30 92 15.5 20 2/4 15' 4" \$50,090.96 \$55,100 30 96 15.5 20 2/4 15' 4" \$52,269.47 \$57,496 30 100 15.5 20 2/4 15' 4" \$54,446.33 \$59,896 35 24 10.5 16 1/4 10' 4" \$12,614.98 \$13,876 35 28 10.5 16 1/4 10' 4" \$13,823.24 \$15,209 35 32 10.5 16 1/4 10' 4" \$15,029.95 \$16,532 35 36 10.5 16 1/4 10' 4" \$15,029.95 \$16,532 35 36 10.5 16 1/4 10' 4" \$16,236.65 \$17,860 35 40 10.5 16 1/4 10' 4" \$17,443.35 \$19,181							\$52,703.68
30 96 15.5 20 2/4 15' 4" \$52,269.47 \$57,490 30 100 15.5 20 2/4 15' 4" \$54,446.33 \$59,890 35 24 10.5 16 1/4 10' 4" \$12,614.98 \$13,876 35 28 10.5 16 1/4 10' 4" \$13,823.24 \$15,209 35 32 10.5 16 1/4 10' 4" \$15,029.95 \$16,532 35 36 10.5 16 1/4 10' 4" \$15,029.95 \$16,532 35 36 10.5 16 1/4 10' 4" \$16,236.65 \$17,860 35 36 10.5 16 1/4 10' 4" \$17,443.35 \$19,181							\$55,100.05
30 100 15.5 20 2/4 15' 4" \$54,446.33 \$59,890 35 24 10.5 16 1/4 10' 4" \$12,614.98 \$13,876 35 28 10.5 16 1/4 10' 4" \$13,823.24 \$15,209 35 32 10.5 16 1/4 10' 4" \$15,029.95 \$16,532 35 36 10.5 16 1/4 10' 4" \$16,236.65 \$17,860 35 36 10.5 16 1/4 10' 4" \$16,236.65 \$17,860 35 40 10.5 16 1/4 10' 4" \$17,443.35 \$19,180	30	96		20 2/4	15' 4"		\$57,496.42
35 24 10.5 16 1/4 10' 4" \$12,614.98 \$13,876 35 28 10.5 16 1/4 10' 4" \$13,823.24 \$15,203 35 32 10.5 16 1/4 10' 4" \$15,029.95 \$16,532 35 36 10.5 16 1/4 10' 4" \$16,236.65 \$17,860 35 36 10.5 16 1/4 10' 4" \$16,236.65 \$17,860 35 40 10.5 16 1/4 10' 4" \$17,443.35 \$19,185	30	100			15' 4"		\$59,890.96
35 28 10.5 16 1/4 10' 4" \$13,823.24 \$15,209 35 32 10.5 16 1/4 10' 4" \$15,029.95 \$16,532 35 32 10.5 16 1/4 10' 4" \$15,029.95 \$16,532 35 36 10.5 16 1/4 10' 4" \$16,236.65 \$17,860 35 40 10.5 16 1/4 10' 4" \$17,443.35 \$19,183	35				10' 4"		\$13,876.47
35 32 10.5 16 1/4 10' 4" \$15,029.95 \$16,532 35 36 10.5 16 1/4 10' 4" \$16,236.65 \$17,860 35 40 10.5 16 1/4 10' 4" \$17,443.35 \$19,183							\$15,205.57
35 36 10.5 16 1/4 10' 4" \$16,236.65 \$17,860 35 40 10.5 16 1/4 10' 4" \$17,443.35 \$19,185							\$16,532.94
35 40 10.5 16 1/4 10' 4" \$17,443.35 \$19,18							\$17,860.31
						. ,	\$19,187.69
35 44 10.5 16 1/4 10' 4" \$18,657.86 \$20,52	35	44	10.5	16 1/4	10' 4"	\$18,657.86	\$20,523.65
							\$21,857.89
							\$23,192.14
							\$24,526.38
							\$25,860.62
							\$27,188.00
							\$28,513.65
							\$29,841.03
							\$31,168.40
							\$32,494.06

Width	Length	Eave Height	Peak Height	Truss Clearance	GSA West	GSA East
35	84	10.5	16 1/4	10' 4"	\$30,746.76	\$33,821.44
35	88	10.5	16 1/4	10' 4"	\$31,953.46	\$35,148.81
35	92	10.5	16 1/4	10' 4"	\$33,158.61	\$36,474.47
35	96	10.5	16 1/4	10' 4"	\$34,365.31	\$37,801.84
35	100	10.5	16 1/4	10' 4"	\$35,572.01	\$39,129.22
35	24	11.5	17 1/4	11' 4"	\$13,294.04	\$14,623.44
35	28	11.5	17 1/4	11' 4"	\$14,592.85	\$16,052.13
35	32	11.5	17 1/4	11' 4"	\$15,893.21	\$17,482.54
35	36	11.5	17 1/4	11' 4"	\$17,192.02	\$18,911.22
35	40	11.5	17 1/4	11' 4"	\$18,490.83	\$20,339.91
35	44	11.5	17 1/4	11' 4"	\$19,794.32	\$21,773.75
35	48	11.5	17 1/4	11' 4"	\$21,097.81	\$23,207.59
35	52	11.5	17 1/4	11' 4"	\$22,401.30	\$24,641.43
35	56	11.5	17 1/4	11' 4"	\$23,706.35	\$26,076.99
35	60	11.5	17 1/4	11' 4"	\$25,009.84	\$27,510.83
35	64	11.5	17 1/4	11' 4"	\$26,303.97	\$28,934.36
35	68	11.5	17 1/4	11' 4"	\$27,599.65	\$30,359.61
35	72	11.5	17 1/4	11' 4"	\$28,895.33	\$31,784.87
35	76	11.5	17 1/4	11' 4"	\$30,189.46	\$33,208.40
35	80	11.5	17 1/4	11' 4"	\$31,485.14	\$34,633.66
35	84	11.5	17 1/4	11' 4"	\$32,779.27	\$36,057.19
35	88	11.5	17 1/4	11' 4"	\$34,074.95	\$37,482.45
35	92	11.5	17 1/4	11' 4"	\$35,369.08	\$38,905.98
35	96	11.5	17 1/4	11' 4"	\$36,664.76	\$40,331.24
35	100	11.5	17 1/4	11' 4"	\$37,958.89	\$41,754.77
35	24	12.5	18 1/4	12' 4"	\$13,787.34	\$15,166.07
35	28	12.5	18 1/4	12' 4"	\$15,535.73	\$17,089.30
35	32	12.5	18 1/4	12' 4"	\$17,302.86	\$19,033.14
35	36	12.5	18 1/4	12' 4"	\$19,069.98	\$20,976.98
35	40	12.5	18 1/4	12' 4"	\$20,816.82	\$22,898.50
35	44	12.5	18 1/4	12' 4"	\$22,538.67	\$24,792.54
35	48	12.5	18 1/4	12' 4"	\$24,588.35	\$27,047.19
35	52	12.5	18 1/4	12' 4"	\$26,638.03	\$29,301.84
35	56	12.5	18 1/4	12' 4"	\$28,686.15	\$31,554.77
35	60	12.5	18 1/4	12' 4"	\$30,735.83	\$33,809.42
35	64	12.5	18 1/4	12' 4"	\$32,785.51	\$36,064.06
35	68	12.5	18 1/4	12' 4"	\$34,833.63	\$38,316.99
35	72	12.5	18 1/4	12' 4"	\$36,883.31	\$40,571.64
35	76	12.5	18 1/4	12' 4"	\$38,931.43	\$42,824.57
35	80	12.5	18 1/4	12' 4"	\$40,981.11	\$45,079.22
35	84	12.5	18 1/4	12' 4"	\$43,030.79	\$47,333.87
35	88	12.5	18 1/4	12' 4"	\$45,078.91	\$49,586.80
35	92	12.5	18 1/4	12' 4"	\$47,128.59	\$51,841.45
35	96	12.5	18 1/4	12' 4"	\$49,178.27	\$54,096.09
35	100	12.5	18 1/4	12' 4"	\$51,226.39	\$56,349.03
35	24	13.5	19 1/4	13' 4"	\$14,890.32	\$16,379.36
35	28	13.5	19 1/4	13' 4"	\$16,778.59	\$18,456.45
35	32	13.5	19 1/4	13' 4"	\$18,687.09	\$20,555.79
35	36	13.5	19 1/4	13' 4"	\$20,595.58	\$22,655.14
35	40	13.5	19 1/4	13' 4"	\$22,482.16	\$24,730.38
35	44	13.5	19 1/4	13' 4"	\$24,341.77	\$26,775.94
35	48	13.5	19 1/4	13' 4"	\$26,555.42	\$29,210.96
35	52	13.5	19 1/4	13' 4"	\$28,769.08	\$31,645.98 uthorized Price I

Width	Length	Eave Height	Peak Height	Truss Clearance	GSA West	GSA East
35	56	13.5	19 1/4	13' 4"	\$30,981.04	\$34,079.15
35	60	13.5	19 1/4	13' 4"	\$33,194.70	\$36,514.17
35	64	13.5	19 1/4	13' 4"	\$35,408.35	\$38,949.19
35	68	13.5	19 1/4	13' 4"	\$37,620.32	\$41,382.35
35	72	13.5	19 1/4	13' 4"	\$39,833.98	\$43,817.37
35	76	13.5	19 1/4	13' 4"	\$42,045.94	\$46,250.54
35	80	13.5	19 1/4	13' 4"	\$44,259.60	\$48,685.56
35	84	13.5	19 1/4	13' 4"	\$46,473.25	\$51,120.58
35	88	13.5	19 1/4	13' 4"	\$48,685.22	\$53,553.74
35	92	13.5	19 1/4	13' 4"	\$50,898.87	\$55,988.76
35	96	13.5	19 1/4	13' 4"	\$53,112.53	\$58,423.78
35	100	13.5	19 1/4	13' 4"	\$55,324.50	\$60,856.95
35	24	14.5	20 1/4	14' 4"	\$15,993.31	\$17,592.64
35	28	14.5	20 1/4	14' 4"	\$18,021.45	\$19,823.59
35	32	14.5	20 1/4	14' 4"	\$20,071.31	\$22,078.45
35	36	14.5	20 1/4	14' 4"	\$22,121.18	\$24,333.30
35	40	14.5	20 1/4	14' 4"	\$24,147.51	\$26,562.26
35	44	14.5	20 1/4	14' 4"	\$26,144.86	\$28,759.35
35	48	14.5	20 1/4	14' 4"	\$28,522.49	\$31,374.74
35	52	14.5	20 1/4	14' 4"	\$30,900.12	\$33,990.13
35	56	14.5	20 1/4	14' 4"	\$33,275.94	\$36,603.53
35	60	14.5	20 1/4	14' 4"	\$35,653.56	\$39,218.92
35	64	14.5	20 1/4	14' 4"	\$38,031.19	\$41,834.31
35	68	14.5	20 1/4	14' 4"	\$40,407.01	\$44,447.71
35	72	14.5	20 1/4	14' 4"	\$42,784.64	\$47,063.10
35	76	14.5	20 1/4	14' 4"	\$45,160.46	\$49,676.50
35	80	14.5	20 1/4	14' 4"	\$47,538.09	\$52,291.90
35	84	14.5	20 1/4	14' 4"	\$49,915.72	\$54,907.29
35	88	14.5	20 1/4	14' 4"	\$52,291.53	\$57,520.69
35	92	14.5	20 1/4	14' 4"	\$54,669.16	\$60,136.08
35	96	14.5	20 1/4	14' 4"	\$57,046.79	\$62,751.47
35	100	14.5	20 1/4	14' 4"	\$59,422.61	\$65,364.87
35	24	15.5	21 1/4	15' 4"	\$17,096.30	\$18,805.93
35	28	15.5	21 1/4	15' 4"	\$19,264.31	\$21,190.74
35	32	15.5	21 1/4	15' 4"	\$21,455.54	\$23,601.10
35	36	15.5	21 1/4	15' 4"	\$23,646.78	\$26,011.46
35	40	15.5	21 1/4	15' 4"	\$25,812.85	\$28,394.14
35	44	15.5	21 1/4	15' 4"	\$27,947.96	\$30,742.75
35	48	15.5	21 1/4	15' 4"	\$30,489.56	\$33,538.51
35	52	15.5	21 1/4	15' 4"	\$33,031.16	\$36,334.28
35	56	15.5	21 1/4	15' 4"	\$35,570.83	\$39,127.91
35	60	15.5	21 1/4	15' 4"	\$38,112.43	\$41,923.67
35	64	15.5	21 1/4	15' 4"	\$40,654.03	\$44,719.44
35	68	15.5	21 1/4	15' 4"	\$43,193.70	\$47,513.07
35	72	15.5	21 1/4	15' 4"	\$45,735.30	\$50,308.84
35	76	15.5	21 1/4	15' 4"	\$48,274.97	\$53,102.47
35	80	15.5	21 1/4	15' 4"	\$50,816.58	\$55,898.23
35	84	15.5	21 1/4	15' 4"	\$53,358.18	\$58,694.00
35	88	15.5	21 1/4	15' 4"	\$55,897.85	\$61,487.63
35	92	15.5	21 1/4	15' 4"	\$58,439.45	\$64,283.39
35	96	15.5	21 1/4	15' 4"	\$60,981.05	\$67,079.16
35	100	15.5	21 1/4	15' 4"	\$63,520.72	\$69,872.79
40	24	10.5	17 1/4	10' 4"	\$12,110.38	\$13,321.41

Width	Length	Eave Height	Peak Height	Truss Clearance	GSA West	GSA East
40	28	10.5	17 1/4	10' 4"	\$13,270.31	\$14,597.34
40	32	10.5	17 1/4	10' 4"	\$14,428.75	\$15,871.62
40	36	10.5	17 1/4	10' 4"	\$15,587.18	\$17,145.90
40	40	10.5	17 1/4	10' 4"	\$16,745.62	\$18,420.18
40	44	10.5	17 1/4	10' 4"	\$17,911.55	\$19,702.70
40	48	10.5	17 1/4	10' 4"	\$19,075.98	\$20,983.58
40	52	10.5	17 1/4	10' 4"	\$20,240.41	\$22,264.45
40	56	10.5	17 1/4	10' 4"	\$21,404.84	\$23,545.32
40	60	10.5	17 1/4	10' 4"	\$22,569.27	\$24,826.20
40	64	10.5	17 1/4	10' 4"	\$23,727.71	\$26,100.48
40	68	10.5	17 1/4	10' 4"	\$24,884.64	\$27,373.11
40	72	10.5	17 1/4	10' 4"	\$26,043.08	\$28,647.39
40	76	10.5	17 1/4	10' 4"	\$27,201.52	\$29,921.67
40	80	10.5	17 1/4	10' 4"	\$28,358.45	\$31,194.30
40	84	10.5	17 1/4	10' 4"	\$29,516.89	\$32,468.58
40	88	10.5	17 1/4	10' 4"	\$30,675.32	\$33,742.86
40	92	10.5	17 1/4	10' 4"	\$31,832.26	\$35,015.49
40	96	10.5	17 1/4	10' 4"	\$32,990.70	\$36,289.77
40	100	10.5	17 1/4	10' 4"	\$34,149.13	\$37,564.05
40	24	11.5	18 1/4	11' 4"	\$13,977.73	\$15,375.51
40	28	11.5	18 1/4	11' 4"	\$15,343.34	\$16,877.67
40	32	11.5	18 1/4	11' 4"	\$16,710.58	\$18,381.64
40	36	11.5	18 1/4	11' 4"	\$18,076.18	\$19,883.80
40	40	11.5	18 1/4	11' 4"	\$19,441.79	\$21,385.96
40	44	11.5	18 1/4	11' 4"	\$20,812.31	\$22,893.54
40	48	11.5	18 1/4	11' 4"	\$22,182.84	\$24,401.12
40	52	11.5	18 1/4	11' 4"	\$23,553.37	\$25,908.70
40	56	11.5	18 1/4	11' 4"	\$24,925.53	\$27,418.09
40	60	11.5	18 1/4	11' 4"	\$26,296.06	\$28,925.67
40	64	11.5	18 1/4	11' 4"	\$27,656.74	\$30,422.41
40	68	11.5	18 1/4	11' 4"	\$29,019.06	\$31,920.97
40	72	11.5	18 1/4	11' 4"	\$30,381.38	\$33,419.52
40	76	11.5	18 1/4	11' 4"	\$31,742.06	\$34,916.27
40	80	11.5	18 1/4	11' 4"	\$33,104.38	\$36,414.82
40	84	11.5	18 1/4	11' 4"	\$34,465.06	\$37,911.56
40	88	11.5	18 1/4	11' 4"	\$35,827.38	\$39,410.12
40	92	11.5	18 1/4	11' 4"	\$37,188.06	\$40,906.86
40	96	11.5	18 1/4	11' 4"	\$38,550.38	\$42,405.42
40	100	11.5	18 1/4	11' 4"	\$39,911.06	\$43,902.16
40	24	12.5	19 1/4	12' 4"	\$15,756.96	\$17,332.65
40	28	12.5	19 1/4	12' 4"	\$17,755.12	\$19,530.63
40	32	12.5	19 1/4	12' 4"	\$19,774.69	\$21,752.16
40	36	12.5	19 1/4	12' 4"	\$21,794.27	\$23,973.69
40	40	12.5	19 1/4	12' 4"	\$23,790.65	\$26,169.71
40	44	12.5	19 1/4	12' 4"	\$25,758.48	\$28,334.33
40	48	12.5	19 1/4	12' 4"	\$28,100.98	\$30,911.07
40	52	12.5	19 1/4	12' 4"	\$30,443.47	\$33,487.81
40	56	12.5	19 1/4	12' 4"	\$32,784.17	\$36,062.59
40	60	12.5	19 1/4	12' 4"	\$35,126.67	\$38,639.33
40	64	12.5	19 1/4	12' 4"	\$37,469.16	\$41,216.07
40	68	12.5	19 1/4	12' 4"	\$39,809.86	\$43,790.85
40	72	12.5	19 1/4	12' 4"	\$42,152.35	\$46,367.59
40	76	12.5	19 1/4	12' 4"	\$44,493.06	\$48,942.37

				Truss		
Width	Length	Eave Height	Peak Height	Clearance	GSA West	GSA East
40	80	12.5	19 1/4	12' 4"	\$46,835.55	\$51,519.11
40	84	12.5	19 1/4	12' 4"	\$49,178.04	\$54,095.85
40	88	12.5	19 1/4	12' 4"	\$51,518.75	\$56,670.63
40	92	12.5	19 1/4	12' 4"	\$53,861.24	\$59,247.37
40	96	12.5	19 1/4	12' 4"	\$56,203.73	\$61,824.11
40	100	12.5	19 1/4	12' 4"	\$58,544.44	\$64,398.89
40	24	13.5	20 1/4	13' 4"	\$17,017.51	\$18,719.26
40	28	13.5	20 1/4	13' 4"	\$19,175.53	\$21,093.08
40	32	13.5	20 1/4	13' 4"	\$21,356.67	\$23,492.34
40	36	13.5	20 1/4	13' 4"	\$23,537.81	\$25,891.59
40	40	13.5	20 1/4	13' 4"	\$25,693.90	\$28,263.29
40	44	13.5	20 1/4	13' 4"	\$27,819.16	\$30,601.08
40	48	13.5	20 1/4	13' 4"	\$30,349.05	\$33,383.96
40	52	13.5	20 1/4	13' 4"	\$32,878.94	\$36,166.84
40	56	13.5	20 1/4	13' 4"	\$35,406.91	\$38,947.60
40	60	13.5	20 1/4	13' 4"	\$37,936.80	\$41,730.48
40	64	13.5	20 1/4	13' 4"	\$40,466.69	\$44,513.36
40	68	13.5	20 1/4	13' 4"	\$42,994.65	\$47,294.12
40	72	13.5	20 1/4	13' 4"	\$45,524.54	\$50,077.00
40	76	13.5	20 1/4	13' 4"	\$48,052.51	\$52,857.76
40	80	13.5	20 1/4	13' 4"	\$50,582.40	\$55,640.64
40	84	13.5	20 1/4	13' 4"	\$53,112.29	\$58,423.52
40	88	13.5	20 1/4	13' 4"	\$55,640.25	\$61,204.28
40	92	13.5	20 1/4	13' 4"	\$58,170.14	\$63,987.16
40	96	13.5	20 1/4	13' 4"	\$60,700.03	\$66,770.04
40	100	13.5	20 1/4	13' 4"	\$63,228.00	\$69,550.80
40	24	14.5	21 1/4	14' 4"	\$18,278.07	\$20,105.88
40	28	14.5	21 1/4	14' 4"	\$20,595.94	\$22,655.53
40	32	14.5	21 1/4	14' 4"	\$22,938.65	\$25,232.51
40	36	14.5	21 1/4	14' 4"	\$25,281.35	\$27,809.49
40	40	14.5	21 1/4	14' 4"	\$27,597.15	\$30,356.87
40	44	14.5	21 1/4	14' 4"	\$29,879.84	\$32,867.83
40	48	14.5	21 1/4	14' 4"	\$32,597.13	\$35,856.84
40	52	14.5	21 1/4	14' 4"	\$35,314.42	\$38,845.86
40	56	14.5	21 1/4	14' 4"	\$38,029.64	\$41,832.61
40	60	14.5	21 1/4	14' 4"	\$40,746.93	\$44,821.62
40	64	14.5	21 1/4	14' 4"	\$43,464.22	\$47,810.64
40	68	14.5	21 1/4	14' 4"	\$46,179.44	\$50,797.39
40	72	14.5	21 1/4	14' 4"	\$48,896.73	\$53,786.40
40	76	14.5	21 1/4	14' 4"	\$51,611.95	\$56,773.15
40	80	14.5	21 1/4	14' 4"	\$54,329.24	\$59,762.17
40	84	14.5	21 1/4	14' 4"	\$57,046.53	\$62,751.18
40	88	14.5	21 1/4	14' 4"	\$59,761.75	\$65,737.93
40	92	14.5	21 1/4	14' 4"	\$62,479.04	\$68,726.95
40	96	14.5	21 1/4	14' 4"	\$65,196.33	\$71,715.97
40	100	14.5	21 1/4	14' 4"	\$67,911.55	\$74,702.71
40	24	15.5	22 1/4	15' 4"	\$19,538.63	\$21,492.49
40	28	15.5	22 1/4	15' 4"	\$22,016.35	\$24,217.98
40	32	15.5	22 1/4	15' 4"	\$24,520.62	\$26,972.68
40	36	15.5	22 1/4	15' 4"	\$27,024.89	\$29,727.38
40	40	15.5	22 1/4	15' 4"	\$29,500.40	\$32,450.44
10	44	15.5	22 1/4	15' 4"	\$31,940.52	\$35,134.57
40 40	44	15.5	22 1/4	15'4"	\$31,940.5Z	φ <u></u> 30,134.57

				Truss		
Width	Length	Eave Height	Peak Height	Clearance	GSA West	GSA East
40	52	15.5	22 1/4	15' 4"	\$37,749.90	\$41,524.89
40	56	15.5	22 1/4	15' 4"	\$40,652.38	\$44,717.61
40	60	15.5	22 1/4	15' 4"	\$43,557.06	\$47,912.77
40	64	15.5	22 1/4	15' 4"	\$46,461.75	\$51,107.93
40	68	15.5	22 1/4	15' 4"	\$49,364.23	\$54,300.65
40	72	15.5	22 1/4	15' 4"	\$52,268.92	\$57,495.81
40	76	15.5	22 1/4	15' 4"	\$55,171.40	\$60,688.54
40	80	15.5	22 1/4	15' 4"	\$58,076.09	\$63,883.69
40	84	15.5	22 1/4	15' 4"	\$60,980.78	\$67,078.85
40	88	15.5	22 1/4	15' 4"	\$63,883.25	\$70,271.58
40	92	15.5	22 1/4	15' 4"	\$66,787.94	\$73,466.74
40	96	15.5	22 1/4	15' 4"	\$69,692.63	\$76,661.89
40	100	15.5	22 1/4	15' 4"	\$72,595.11	\$79,854.62

CUSTOM SIZES ARE AVAILABLE!

Pricing for custom sizes is calculated as follows:

Divide the Size increment to be changed by the list price of the next largest building to obtain unit price. Multiply unit price by the desired size to obtain custom size list price.

Example:

Desired Building Size is **23'** wide x 24' long x 10.5 high Next largest Stock Size Building is **24'** wide x 24' long x 10.5 high. List Price is \$10,000.00 CALCULATE UNIT PRICE: \$10,000.00 / 24 = \$416.67 CALCULATE CUSTOM BUILDING LIST PRICE: \$416.67 * 23 = \$9,583.41